

TOP SECRET

12 JAN 1963

PRIORITY

TOP SECRET 112109Z

(OUT 50446)<sup>25X1</sup>

CORONA M

REF: MISSION 9050 - M17

HFS  
CS  
acc

1. BINARY TIME MALFUNCTIONS OF FORWARD CAMERA WERE:

- A. LIGHT NO. 12 VERY DIM.
- B. LIGHT NO. 10 WAS WIRED INCORRECT AND SHOULD HAVE BEEN NO. 9.
- C. LIGHT NO. 9 SHOULD HAVE BEEN NO. 8.
- D. LIGHT NO. 8 SHOULD HAVE BEEN NO. 10.

2. BINARY INDEX LIGHTS AND CAMERA NUMBER ON AFT CAMERA FAILED AFTER PRE-FLIGHT. THIS GREATLY COMPLICATED BINARY READOUT.

3. NO OTHER LIGHT FAILURES OCCURRED.

TOP SECRET

CFN: 0429 9050 M17 12 10 9 9 8 8 10 AFT

1963 JAN 11 21 34Z

BT

125

NNNN

25X1

TOP SECRET